

# SHOCKWATCH LABEL - HOW TO MOUNT IT

## Rules of thumb:

1. Always place labels on right edge of shipment.
2. The heavier the shipment, the lower you should mount the label.

LABEL	PLACEMENT	EXCEPTIONS
GREEN L-30	Upper right corner near packing slip	N/A
ORANGE L-30	Upper right corner near packing slip	N/A
RED L-47	Upper right corner of shipment	If palletized, place on right 24" from floor
PURPLE L-55	50-100 lbs. - upper right corner 100 -500 lbs. - right edge of shipment 12-24" from floor	On large items where length is twice the width, use 2 labels on opposite sides of shipment, diagonally from one another.
YELLOW L-65	Right edge of shipment 12-24" from floor	


## L-30 Green - 100G at 50 msec.

Product examples:

- Avionics equipment
- Service/repair electronics
- Home accessories
- Instrumentation/gauges
- Computer removable fixed media
- Audio/visual equipment
- Computer equipment
- Electro mechanical equipment
- Any UPS shipment
- Tapes, multi-platter disk packs

### Placement of Labels

Placement is in upper right corner of box nearest packing slip.




## L-35 Orange - 75G at 50 msec.

Product examples:

- Avionics instruments
- Auto parts
- Computer equipment
- Lamps/china/porcelains
- Hard drives
- Furniture (chairs, cabinets)
- Medical equipment
- Electro mechanical equipment
- Neon sign parts
- Home accessories
- Art/sculpture
- Displays/exhibits

### Placement of Labels

Placement is in upper right corner of box nearest packing slip.




## L-47 Red - 50G at 50 msec.

Product examples:

- Audio visual/broadcast equipment
- Auto parts
- Computer equipment
- Furniture
- Restaurant equipment
- Medical equipment
- Electro mechanical equipment
- Sheet metal
- Neon signs
- Art/sculpture
- Display/exhibits

### Placement of Labels

1. On large items or palletized shipments, label is placed on right edge, 24" from floor.
2. On other items, placement from 24" to upper right corner of unit side is adequate.





## L-55 Purple - 37G at msec.

Product examples:

- Auto parts
- Restaurant equipment
- Sheet metal
- Bulk shipping of several items on one pallet
- Medical equipment
- Copiers/printers
- Heavy furniture/art/sculpture
- Displays/exhibits
- Computer equipment

### Placement of Labels

1. 50-100 lbs. - middle to upper right edge of carton  
100-500 lbs. - 12" to 24" from floor, right edge
2. On large items or palletized shipments, use 2 labels per shipment. Place labels on opposite sides of carton diagonally from one another.



On large items where length is twice the width, place 2 labels diagonally from one another on opposite sides of the carton.


## L-65 Yellow - 25G at 50 msec.

Product examples:


- Bulk shipping of several items on one pallet
- Printers/computers weighing over 300 lbs.
- Heavy furniture
- Displays/exhibits

### Placement of Labels

1. Place Shockwatch Label 12" to 14" from floor.
2. On large items or palletized shipments, use 2 labels per shipment. Place labels on opposite sides of carton diagonally from one another.



Place second label on other side of shipment on rear right side (in same area) to cover monitoring of total shipment.



On large items where length is twice the width, place 2 labels diagonally from one another on opposite sides of the carton.